
1/7






FIG. 2

2/7




FIG. 3




FIG. 4

3/7




FIG. 5






FIG. 6



5/7
LOCATE THE UPPER AND LOWER WIRES:



^{* - &}lt;u>if required mandibular distalization > 4mm then</u> molar movement is not possible




FIG. 8




FIG. 9

